

	Boisé	Date	N° local	Type de local	Robinnet	Buvette	Résultat
1	824-005-001P0	27-mars-20	SRM R-6	Corridor		✓	<2,0
2	824-005-001P30	27-mars-20	SRM R-6	Corridor		✓	<2,0
3	824-005-002P0	27-mars-20	SRM R-19	Corridor		✓	<2,0
4	824-005-002P30	27-mars-20	SRM R-19	Corridor		✓	<2,0
5	824-005-003P0	27-mars-20	SRM R-38	SDG	✓		<2,0
6	824-005-003P30	27-mars-20	SRM R-38	SDG	✓		<2,0
7	824-005-004P0	27-mars-20	SRM R-23	Corridor		✓	<2,0
8	824-005-004P30	27-mars-20	SRM R-23	Corridor		✓	<2,0
9	824-005-005P0	27-mars-20	SRM R-23	Corridor		✓	<2,0
10	824-005-005P30	27-mars-20	SRM R-23	Corridor		✓	<2,0

Bilan

Établissement: Boisé

Nbr points d'eau analysé: 5

Nbr points d'eau conforme: 5

Nbr points d'eau non conforme:

	Conforme en tout temps	Conforme après que l'eau ait coulé 30 secondes	Non conforme
Nbr robinets	1		
Nbr buvettes	4		
Mesure de mitigation mise en place	Point d'eau demeure accessible		

P0s : échantillon prélevé après la période de stagnation de 6h

P030s: échantillon prélevé après 30 secondes d'écoulement